

APPENDIX G: CULVERT REPLACEMENTS

Summary of culvert sites identified needing replacement during the 2015 watershed survey by LWA and FB Environmental.

Site ID	Location	Land Use	Issues	Recommendations	Impact High = 3 Med = 2 Low = 1	BMP Cost Estimate	BMP Annual Maintenance Cost Estimate	10-yr Cost
1-01	Town Hall Parking Lot	Town Road	Slight surface erosion, culvert too short, winter sand present.	Lengthen culvert, remove winter sand.	1	\$2,250	\$25	\$2,500
1-15	Evans Road	Town Road	Undersized culvert (should be a bridge) and undercut shoreline.	Replace culvert with a bridge/enlarge.	2	\$5,000	\$25	\$5,250
1-17	Bodge Hill Road Pole 18020-15	Town Road	Seep breaks out onto the road.	Install perforated culvert under road.	1	\$1,500	\$25	\$1,750
1-51	Lee Road	Town Road	Undersized culvert, undercut shoreline	Enlarge culvert	2	\$2,000	\$25	\$2,250
1-55	Lee's Mill Road	Town Road	Undersized culvert.	Enlarge and reposition culvert.	1	\$1,500	\$25	\$1,750
2-01	Paradise Drive	Town Road	Culvert - misaligned/ poorly designed.	Replace culvert.	3	\$3,000	\$25	\$3,250
TOTAL						\$15,250	\$150	\$16,750